

**GREG BELL** Lieutenant Governor

## State of Utah

#### DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection:					
Company	Rusty Netz				
OGM	Karl Houskeeper				



# **Inspection Report**

Permit Number:	C0070035		
Inspection Type:	PARTIAL		
Inspection Date:	Tuesday, July 20, 2010		
Start Date/Time:	7/20/2010 9:00:00 AM		
End Date/Time:	7/20/2010 12:00:00 PM		
Last Inspection:	Wednesday, June 09, 2010		

Inspector: Karl Houskeeper,

Weather: Partly Cloudy, Temp. 81 Deg. F.

InspectionID Report Number: 2428

Accepted by: jhelfric 7/29/2010

Permitee: SUNNYSIDE COGENERATION ASSOCIATES Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: SUNNYSIDE REFUSE & SLURRY

Address: .

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

**Current Acreages** 

<b>Total Permitted</b>	
<b>Total Disturbed</b>	202.00
Phase I	5.50
Phase II	
Phase III	

Mineral Ownership

**Types of Operations** 

Underground

☐ Surface State Loadout County

**✓** Fee Processing Other ✓ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Butch Hansen, Savage, accompanied Rusty Netz, SCA, and Karl Houskeeper, OGM, on the inspection.

Inspector's Signature:

Date

Tuesday, July

Karl Houskeeper,

Inspector ID Number: 49

Permit Number: C0070035 Inspection Type: PARTIAL

Inspection Date: Tuesday, July 20, 2010

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	~		<b>✓</b>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
<u>4.d</u>	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
<u>5.</u>	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
<u>7.</u>	Coal Mine Waste, Refuse Piles, Impoundments	V		<b>✓</b>	
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	Roads: Construction, Maintenance, Surfacing				
16.t	Roads: Drainage Controls				
<u>17.</u>	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

**Inspection Continuation Sheet** 

Permit Number: C0070035 Inspection Type: PARTIAL

Inspection Date: Tuesday, July 20, 2010

Page 3 of 3

#### 2. Signs and Markers

A mine identification sign needs to be installed at the point of public access to the permit area or the area accessed off from the road to Columbia.

#### 4.a Hydrologic Balance: Diversions

Minor maintenance work is needed on a few diversions throughout the dsturbed area.

### 7. Coal Mine Waste, Refuse Piles, Impoundments

Large erosion cuts on the face of the refuse pile, Northern side lower two terraces needs to be repaired.